天祺科技股份有限公司 **Inspection Report** Contact Person YUYI DRT-A626/1096010-1022 Serial No. DRT overhaul Product Customer DRT-A626 Maker/model Test Date 1096010-1022 Serial Number 備註/Note. 項目Item 內容描述/Content description 異常狀況 無訊號,雷達圖打不開 Abnormal condition No signal, radar chart cannot be opened 產品外觀檢查 產品外觀檢查正常/Pass Appearance inspection 1.上機測試故障雷達圖打不開,無信號/ On-board test failure radar chart can not be opened, no signal 主要功能檢驗 Main function inspection 2.打開DRT進行檢查,RT部分正常(如右圖)-----> RT part is normal (as shown in the right picture) DRT主板有毀損,需要更換零件,採頭部分亦有毀損 檢驗結果 The DRT motherboard is damaged, parts need to be replaced, and the probe part is also damaged 1.更换DRT主電路板內部零件Replace the internal parts of the DRT main circuit board 維修內容 Repair content 2.探頭部分,發現有晶片損壞,更換(如右圖)-----> 2.裝在機台測試DRT雷達圖可以打開,也有翹曲率 1.組裝上電測試,連接在測試電腦上DRT電達可以打開,圖像如下 VCCCO 維修後檢驗 Test after Repair

版图(Alt + A)

Solutions for a nanoscale world.