

Repair Report

Receiving Date

Checking Date

TO: USER:

Parts

Model

EUROTHERM

S/N

3504通訊卡


U002-4015-930-09-HK/U002-2818-711-10-HK

Detail of Trouble:					
Item	Description	Photo	Note		
1	偶爾無法連網 something can't connect				
2					

Description of Service Work :					
Item	Description	Photo	Note		
外觀檢側 Exterior Inspection side	無明顯損傷/PASS				
上機檢測 On-board testing	連接電腦後,出現偶爾會連不上電腦之情況 After connecting to the computer, occasionally it may not be able to connect to the computer		經過檢測發現,部分零件參數 異常 After testing, it was found that some parts parameters were abnormal		

Repair content					
Item	Description	Action	Note		
1	不良零件/Bad parts	Replaced			
2	線路板/circuit board	Cleaned			
INSPECTION					
Item	Description		Note		
1	將EUROTHERM 裝機,連接電源開機顯示正常/ Install EUROTHERM, connect to the power supply, and the display is normal				
2	連接電腦用軟體掃描,可以連接網路並找到EUROT Connect to the computer and scan with software, you car EUROTHERM				
3	使用軟體測試,沒有顯示ERROR/NO ERROR				





REMARK